


Basic fancy Crate



















































Basic non-fancy Crate











Pre-made












Object crates



















Art Frames






materials











Static loading values shown will yield optimum protection / lowest possible G forces for that type and thickness of foam, as shown in right hand column.

Foam Type	Thickness	Static Loading – object lbs. per sq.in. foam (psi)	Static Loading – as sq. in. foam required per object lbs.	G force limited to:
Polyester Urethane	2"	.375 psi.	2.67 sq.in./lb.	37 Gs
Polyester Urethane	4"	.375 psi.	2.67 sq.in./lb.	14 Gs
Ethafoam 220	2"	.67 psi.	1.67 sq.in./lb.	46 Gs
Ethafoam 220	4"	.85 psi.	1.17 sq.in./lb.	24 Gs
Plastazote LD24	2"	~ .5 psi.	~ 2 sq.in./lb.	60 Gs
Ethafoam HS 45	2"	.75 psi.	1.33 sq.in./lb.	54 Gs
Ethafoam HS 600	2"	1.2 psi.	.833 sq.in./lb.	45 Gs
Ethafoam HS 900	2"	2.2 psi.	.454 sq.in./lb.	53 Gs

There's always ULINE

Here are some ULINE alternatives:

SHIPPING SUPPLIES

eastcoastpkg.com

papermart.com

packagingprice.com

prattindustries.com

theboxery.com

crosscorpusa.com

ecoenclose.com

primepackaging.com

bagbarn.com

staplesadvantage.com

INDUSTRIAL SUPPLY

globalindustrial.com

grainger.com

mcmaster.com

CUSTOM

stickergiant.com

lumi.com

stephengould.com


busybeaver.net

labelvalue.com

Bad things happen











What not to do















Tips and tricks








* This instruction is the same to all three boxes.

Please check the received three packages.


Each box has 2 art pieces, 4 steel-wire hooks, and 4 rings.

Each art work tied up with 6 legs. Please handle with care. The legs are fragile.



1. Open the top side where a sign show "open side", using a cutter along with the dots on box tapes.

→ Dots on box tapes




2. Find 4 steel-wire hooks and 4 rings for hanging the art pieces.

Note: see the installation manual.

4 steel -wire hooks and 4 rings in the Ziploc bag.


2/3





3. Take out one of the Styrofoam sides which has a handle. It will make the art pieces out easily.



Lay down the box like the picture.
 Use the box board to grab.
 Take out the art pieces.







Meditation
crystal wafers, polymer plates, chromium,
gold, titanium and copper

Questions?